Approved For Release 2002/05/08 : CIA-RDP78B04767A000100060017-2

SECRET

ACTION COPY

P 152033Z MAR 68
FM NPIC WASHDC
TO DIA
BT
S E C R E T CITE NPIC 3937.

25X1

No RECORD

REF: S-0134XX-2, 23 FEBRUARY 1968
SUBJ: EVALUATION OF MISSION BU 900642 FLOWN 19 DECEMBER 1967.
1. THIS MISSION EMPLOYED CAMERA NUMBER 60 FLOWN IN VEHICLE NUMBER H-32. PROCESSING WAS ACCOMPLISHED BY THE 67TH RECON TECH SQ.
2. ORIGINAL NEGATIVE:
A. EXPOSURE/RESOLUTION: THE DENSITY IS ADQUATE AND THE CONTRAST IS GENERALLY LOW THROUGHOUT THE MISSION. THE RESOLUTION RANGES FROM FAIR TO POOR.
B. CAMERA OPERATION: THE FIRST 19 FRAMES OF THE MISSION CONTAIN MISMETERING, VARYING FORMAT SIZE, AND A ONE SECOND CYCLE RATE ALL OF WHICH ARE ASSOCIATED WITH PRELIGHT CAMERA CHECKOUT. BANDING, PARALLEL TO THE MINOR AXIS IS PRESENT IN EVERY FRAME THROUGHOUT THE ENTIRE MISSION. IT IS APPARENTLY CAUSED BY ERRATIC

3

PAGE 2 RUEPJU 46 S E C R E T
SHUTTER MOVEMENT. THE BANDING IS MORE SEVERE WHEN THE SHUTTER MOVED FROM THE TRAILING END OF THE FORMAT TO THE LEADING END. METERING, VACUUM, AND DATA RECORDING APPEAR TO HAVE OPERATED NORMALLY THROUGHOUT THE MISSION.

ILLEGIB

DECLASS REVIEW by NIMA/DOD

S E C R E T

SECRET

END OF MESSAGE

DROP 1
Excluded from automatic downgrading and declassification

Approved For Release 2002/05/08 : CIA-RDP78B04767A000100060017-2

Approved For Release 2002/05/08 : CIA-RDP78B04767A000100060017-2

22601-8

SIEB Cable Routing Slip

BUQ642

	To	Initials
	PMO/SIEB	T.F.
	Ch/SIEB	
1	Dep Ch/SIEB	
	Ch/Systems A Section	
2	Ch/Systems B Section	2K
	Ch/SPS	
	Ch/Micro-D Section	
	SIEB Secretary	

OUT CABLE!

COMMENTS:

CHECK CONTENT!

Approved For Release 2002/05/08 : CIA-RDP78B04767A000100060017-2